

MATERIAL SAFETY DATA SHEET

SECTION 1 PRODUCT NAME AND COMPANY IDENTIFICATION

PRODCUT NAME: Econo-print
MANUFACTURER'S NAME: Webster Fabric
MANUFACTURER'S ADDRESS: 582 Goddard Ave.
Chesterfield, Mo. 63005
EMERGENCY TELEPHONE NUMBER : 314-532-1614
TELEPHONE NUMBER: 314-532-1614
DATE PREPARED: 5-1-99

SECTION 2 HAZARDOUS COMPONENTS

Benzenedicarboxylic acid CAS-68515-49-1
Vinyl Chloride<.001%PBL CAS-75-01-4

SECTION 3 PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT-----NA
VAPOR PRESSURE-----NA
VAPOR DENSITY-----NA
SOLUBILITY IN WATER-----NA
APPEARANCE AND ODOR-----NA
SURFACE GRAVITY-----NA
MELTING POINT-----NA
EVAPORATION RATE-----NA

SECTION 4 FIRE AND EXPLOSION HAZARDS

FLASH POINT-----NA
FLAMMABLE LIMITS-----NA
EXTINUISHING MEDIA-----WATER, ABC DRY CHEMICAL
SPECIAL FIRE FIGHTING PROCEDURES-----FIREFIGHTERS SHOULD WEAR SELF-CONTAINED BREATHING APPARATUS (SCBA)
UNUSUAL FIRE AND EXPLOSION HAZARDS-----NA

SECTION 5 REACTIVITY DATA

STABILITY-----STABLE
CONDITIONS TO AVOID-----TEMPERATURES ABOVE 600 DEGREES F
INCOMPATILITY (MATERIALS TO AVOID)----STRONG OXIDIZING AGENTS
HAZARDOUS DECOMPOSITION OR BYPRODUCTS—NITROUS GASSES, HYDROGEN CYANIDE AND CARBON MONOXIDE ARE POSSIBLE DECOMPOSITION BY PRODUCTS
POLYMERIZATION---WILL NOT OCCUR

SECTION 6 HEALTH HAZARD DATA

PRIMARY ROUTES OF ENTRY AND FIRST AID PROCEDURES:
SKIN CONTACT: SHOULD MOLTEN MATERIAL CONTACT THE SKIN DURING PROCESSING, COOL AFFECTED AREA WITH WATER AND EXCLUDE AIR. TREAT FOR BURN.

INHALATION: NEGLIGIBLE HAZARD AT AMBIENT TEMPERATURE (0 TO 100 DEGREES F, - 18 TO +38 DEGREES C). VAPORS AND/OR AEROSOLS WHICH MAY BE FORMED AT ELEVATED TEMPERATURES MAY BE IRRITATING TO THE EYES AND RESPIRATORY TRACT. IF A PROBLEM DEVELOPS REMOVE THE PERSON TO FRESH AIR AND SUPPLY OXYGEN IF NECESSARY

INGESTION: MINIMAL TOXICITY. FIRST AID IS NOT NECESSARY

EYE CONTACT: THIS PRODUCT IS AN INERT SOLID. IF IN EYE REMOVE AS ONE WOULD REMOVE ANY FOREIGN OBJECT.

THRESHOLD LIMIT VALUE: NO ESTABLISHED VALUE. PRODUCT IS INERT

EFFECTS OF OVEREXPOSURE: NA

SECTION 7 SPILL OR LEAK PROCEDURES

CLEAN UP: ALLOW TO COOL, SWEEP OR SCRAP INTO SECURE CONTAINERS FOR DISPOSAL.

WASTE DISPOSAL: DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

SECTION 8 STORAGE AND HANDLING

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE: STORE IN A COOL DRY AREA AWAY FROM DIRECT SUNLIGHT.

SECTION 9 SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION: -----NA

LOCAL EXHAUST: ----- NA

PROTECTIVE GLOVES: -----NOT NEEDED

EYE PROTECTION: -----USE OF EYE PROTECTION DURING PROCESSING IS RECOMMENDED WITH ACCEPTED INDUSTRY SAFETY PROCEDURES.

WORK/HYGIENIC PRACTICES: PRACTICE GOOD HYGIENE AFTER HANDLING.

SECTION 10 REGULATORY INFORMATION

TSCA INVENTORY