MATERIAL SAFETY DATA SHEET

SECTION 1 PRODUCT NAME AND COMPANY IDENTIFICATION

PRODCUT NAME: Econo-print

<u>MANUFACTURER'S NAME:</u> Webster Fabric <u>MANUFACTURER'S ADDRESS:</u> 582 Goddard Ave.

Chesterfield, Mo. 63005

EMERGENCY TELEPHONE NUMBER: 636-532-1614

TELEPHONE NUMBER: 636-532-1614

DATE PREPARED: 5-1-99

SECTION 2 HAZARDOUS COMPONETS

Benzenedicarboxlic acid CAS-68515-49-1 Vinyl Chloride<.001% PBL CAS-75-01-4

SECTION 3 PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT-----NA VAPOR PRESSURE-----NA

VAPOR DENSITY-----NA SOLUBILITY

IN WATER-----NA

APPEARANCE AND ODOR-----NA

SURFACE GRAVITY-----NA

MELTING POINT-----NA

EVAPORATION RATE----NA

SECTION 4 FIRE AND EXPLOSION HAZARDS

FLASH POINT-----NA

FLAMMABLE LIMITS----NA

EXTINUISHING MEDIA------WATER, ABC DRY CHEMICAL

SPECIAL FIRE FIGHTING PROCEDURES-----FIREFIGHTERS SHOULD WEAR

SELFCONTAINED BREATHING APPARATUS (SCBA)

UNUSUAL FIRE AND EXPLOSION HAZARDS-----NA

SECTION 5 REACTIVITY DATA

STABILITY-----STABLE

CONDITIONS TO AVOID-----TEMPERATURES ABOVE 600 DEGREES F

INCOMPATILITY (MATERIALS TO AVOID)----STRONG OXIDIZING AGENTS

HAZARDOUS DECOMPOSITION OR BYPRODUCTS—NITROUS GASSES, HYDROGEN

CYANIDE AND CARBON MONOXIDE ARE POSSIBLE DECOMPOSTION BY PRODUCTS POLYMERIZATION---WILL NOT OCCUR

SECTION 6 HEALTH HAZARD DATA

PRIMARY ROUTES OF ENTRY AND FIRST AID PROCEDURES:

SKIN CONTACT: SHOULD MOLTEN MATERIAL CONTACT THE SKIN DURING PROCESSING, COOL AFFECTED AREA WITH WATER AND EXCLUDE AIR. TREAT FOR BURN. INHALATION: NEGLIGIBLE HAZARD AT AMBIENT TEMPERATURE (0 TO 100 DEGREES F, 18 TO +38 DEGREES C). VAPORS AND/OR AEROSOLS WHICH MAY BE FORMED AT ELEVATED TEMPERATURS MAY BE IRRITATIONF TO THE EYES ANS RESPIRATORY TRACT.

IF A PROBLEM DEVLOPS REMOVE THE PERSON TO FRESH AIR AND SUPPLY OXYGEN IF NECESSARY

INGESTION: MINIMAL TOXICITY. FIRST AID IS NOT NECESSARY

EYE CONTACT: THIS PRODUCT IS AN INERT SOLID. IF IN EYE REMOVE AS ONE WOULD REMOVE ANY FOREIGN OBJECT.

THRESHOLD LIMIT VALUE: NO ESTABLISHED VALUE. PRODUCT IS INERT EFFECTS

OF OVEREXPOSURE: NA

SECTION 7 SPILL OR LEAK PROCEDURES

CLEAN UP: ALLOW TO COOL, SWEEP OR SCRAP INTO SECURE CONTAINERS FOR DISPOSAL.

WASTE DISPOSAL: DISPOSE OF IN ACCORDANE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

SECTION 8 STORAGE AND HANDLING

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORGAE: STORE IN A COOL DRY AREA AWAY FROM DIRECT SUNLIGHT.

SECTION 9 SPECIAL PROTESTION INFORAMTION

RESPIRATORY PROTECTION: -----NA

LOCAL EXHAUST: ----- NA

PROTECTIVE GLOVES: -----NOT NEEDED

EYE PROTECTION: -----USE OF EYE PROTECTION DURING PROCESSING IS

RECOMMENDED WITH ACCEPTED INDUSTRY SAFETY PROCEDURES.

WORK/HYGENIC PRACTICES: PRACTICE GOOD HYGIENE AFTER HANDLING.

SECTION 10 REGULATORY INFORAMTION TSCA INVENTORY